

Inspection Photos

Operator: Gunnison Energy

API: 05-051-06077

Date: 7/26/2018



Photo 1. View of the project area from southeastern corner facing center. One well observed.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing with grasses such as smooth brome (*Bromus inermis*) and western wheatgrass (*Pascopyrum smithii*).



Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward.



soils

Photo 4. View of silt trap in the northeastern portion of the project area, appears to be functioning.



soils

Photo 5. View of untreated musk thistles (*Carduus nutans*) and Canada thistles (*Cirsium arvense*) growing along the northern edge of the project area.