

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/13/2018

Submitted Date:

08/14/2018

Document Number:

689701698**FIELD INSPECTION FORM**Loc ID 335403 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Contact Information:**

Contact Name	Phone	Email	Comment
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263979	WELL	PR	12/10/2002	GW	045-08168	FEDERAL PA 44-27	PR
263980	WELL	PR	06/05/2002	GW	045-08169	FEDERAL PA 344-27	PR

**General Comment:**

Follow up to inspection 689701273

Corrective action not completed.

Storm water flow into checkdam (creating erosion rill) has been redirected with damn block and using a culvert to cross road. Ditch and checkdam added to location edge to move storm water flow.

**Location**Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	Label is faded on container at well heads.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 05/18/2018

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 263979 Type: WELL API Number: 045-08168 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 263980 Type: WELL API Number: 045-08169 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [The overflow from check dam north of production tank is creating erosion cut down hillside to roadway below \(GPS Coordinates 39.49054 107.97551\).](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 05/18/2018

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401732817	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4551121">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4551121</a>
689701699	Inspection 689701698 follow up to insp. 689701273	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4551102">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4551102</a>