

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2018

Submitted Date:

08/21/2018

Document Number:

682600540

FIELD INSPECTION FORM

Loc ID 307384 Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10084
Name of Operator: PIONEER NATURAL RESOURCES USA INC
Address: 5205 N O'CONNOR BLVD STE 200
City: IRVING State: TX Zip: 75039

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
White, LaCretia		lacretia.white@pxd.com	all inspections
Lyon, Mark		MLyon@BLM.gov	
Axelson, John		john.axelson@state.co.us	
Morgan, Cheri		cheri.morgan@enrllc.com	
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections
Roybal, James		james.roybal@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217579	WELL	PR	01/05/2003	GW	071-06358	COLORADO 34-16	EI

General Comment:

This inspection is in response to an anonymous complaint alleging that this Colorado 34-16 well was recently re-fracked and a pit dug on the location where fluid was flowed back to the pit during the operations. Complainant alleges that the pit was backfilled with no testing at conclusion of the work.

Observations around the well pad did not find any evidence to suggest that heavy equipment such as a drill rig had recently been on location. No tire tracks or other disturbance of well pad surface was observed. A produced water pit on location was observed to have fluid in it. No signs of another recently backfilled pit on location were observed.

The produced water pit on location is not currently in use. Operator has plumbed in a produced water tank from the wellhead (see attached photos). COGCC records and confirmation with operator indicate that this well has not produced water since 2013. Produced water tank on location did not appear to have any fluid in it.

Produced water pit on location was observed to have stained soil and a green fluid (see attached photos). Fluid and stained soil did not have an odor. Operator was informed of fluid in pit and planned to obtain samples of fluid.

Inspected Facilities

Facility ID: 217579 Type: WELL API Number: 071-06358 Status: PR Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600541	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4558191