

**Inspection Photo
Gentry C9
API # 045-15271
Inspection # 689301780**



Location Photo #1



Location Photo #2, Mark anchor as required.

**Inspection Photo
Gentry C9
API # 045-15271
Inspection # 689301780**



Location Photo #3, Mark anchor as required



Location Photo #4, holes in secondary liner.

**Inspection Photo
Gentry C9
API # 045-15271
Inspection # 689301780**



Location Photo #5, Stained material in battery containment.



Location Photo #6, Stained Material in battery containment.



**Inspection Photo
Gentry C9
API # 045-15271
Inspection # 689301780**



08/21/18

Location Photo #7, Weeds on location



08/21/18

Location Photo #8, weeds on location

**Inspection Photo
Gentry C9
API # 045-15271
Inspection # 689301780**



Location Photo #9, Weeds on access road



Location Photo #10, weeds on location.