

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/21/2018

Submitted Date:

08/21/2018

Document Number:

689301788

FIELD INSPECTION FORM

Loc ID 335551 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10447
Name of Operator: URSA OPERATING COMPANY LLC
Address: 1600 BROADWAY ST STE 2600
City: DENVER State: CO Zip: 80202

Findings:

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293336	WELL	PR	10/01/2017	GW	045-14947	DEVER C9	PR
293337	WELL	PR	11/06/2007	GW	045-14946	DEVER C8	PR
293338	WELL	PR	12/24/2013	GW	045-14945	Dever C7	PR
293341	WELL	PR	05/01/2018	GW	045-14942	DEVER C4	PR
293342	WELL	PR	05/01/2018	GW	045-14941	DEVER C3	PR
293343	WELL	XX	03/12/2018	LO	045-14940	Dever C2	ND

General Comment:

[Routine Field inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Emergency Contact Number:		
Comment:	1-855-625-9922	
Corrective Action:		Date:

Good Housekeeping:		
Type	WEEDS	
Comment:	Weeds along access road	
Corrective Action:	Comply with Rule 603.f .	Date: 08/31/2018

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:	Livestock gates	
Corrective Action:		Date:

Equipment:			corrective date
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	water lines		
Corrective Action:			Date:

Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellhead		
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	Unmarked anchor		
Corrective Action:	Mark as required		Date: 09/21/2018

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		,
Comment:	3 out of service Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Containment damage, see photo			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			
				Date: 09/21/2018

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	293336	Type:	WELL	API Number:	045-14947	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	293337	Type:	WELL	API Number:	045-14946	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	293338	Type:	WELL	API Number:	045-14945	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	293341	Type:	WELL	API Number:	045-14942	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	293342	Type:	WELL	API Number:	045-14941	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	293343	Type:	WELL	API Number:	045-14940	Status:	XX	Insp. Status:	ND

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
		Compaction				
		Gravel				
Ditches						
Seeding						
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301789	Inspection photo 689301789	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4558257