

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/21/2018

Submitted Date:

08/21/2018

Document Number:

689301776**FIELD INSPECTION FORM**

Loc ID 335329 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266558	WELL	SI	11/01/2017	GW	045-09152	KELL 35-4D (B35NW)	PR
266568	WELL	PR	02/19/2004	GW	045-09155	KELL 35-4A (B35NW)	PR
266572	WELL	PR	09/27/2003	GW	045-09158	KELL 35-3D (B35NW)	PR
266573	WELL	PR	02/19/2004	GW	045-09157	KELL 35-3B (B35NW)	PR

General Comment:[On site to witness Bradenhead test](#)

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:	1-800-791-7691	
Corrective Action:		Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type	#	corrective date
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 3	
Comment:		
Corrective Action:		Date:
Type: Vertical Heated Separator	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:				Date:	

Paint

Condition	Inadequate	
Other (Content)	Methanol tank	
Other (Capacity)	1000 gallon	
Other (Type)		

Berms

Inspector Name: Holtz, Darin

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	266558	Type:	WELL	API Number:	045-09152	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	266568	Type:	WELL	API Number:	045-09155	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	266572	Type:	WELL	API Number:	045-09158	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well producing.								
Corrective Action:						Date:			
BradenHead									
Comment:	Bradenhead Test, test performed with a needle valve for a bleed down point. 0833 C-203 psi, T-329 psi, BH 206 psi, gas 0838 C-203 psi, T-329 psi, Gas 0843 C-203 psi, T-329 psi, Gas 0848 C-202 psi, T-329 psi, Gas 0853 C-202 psi, T-329 psi, Gas 0858 C-202 psi, T-329 psi, Gas 0903 C-202psi, T-329psi, BH 26 psi, Gas								
Corrective Action:						Date:			
Facility ID:	266573	Type:	WELL	API Number:	045-09157	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Compaction						
		Compaction				
		Gravel				
Seeding						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301777	Inspection photo 689301777	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4558251