

Final Reclamation Inspection

August 16, 2018

Operator: NANKE ENERGY LLC- #10662

API: 05-039-06608

Inspection Document #: 682403886

Elbert County, CO

SWSE Section 10 T6S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: COGGINS #10-34
API: 05-039-06608



Photo 1. Photo taken from the northern location on November 3, 2017, facing South. Appears the Operator has mowed and seeded the location based on drill row markings.



Photo 2. Photo taken from the northern location on August 16, 2018, facing South. Establishment of desirable species was observed throughout portions of the location. Bare patches were observed and uniform growth has not been achieved- see photos 6-8 and 10. Additional reclamation activities will be required.

Inspection Photos
Location Name: COGGINS #10-34
API: 05-039-06608



Photo 3. Close up photo taken from the northern location on August 16, 2018, illustrating establishment of desirable species, Smooth brome.

Inspection Photos
Location Name: COGGINS #10-34
API: 05-039-06608



Photo 4. Photo taken from the southeastern location on August 16, 2018, facing North. See comments under Photo 2.

Inspection Photos
Location Name: COGGINS #10-34
API: 05-039-06608



Photo 5. Photo taken from the southwestern location on August 16, 2018, facing West. This photo illustrates the vegetative goal that should be achieved throughout the entire location before releasing the location.

Inspection Photos
Location Name: COGGINS #10-34
API: 05-039-06608



Photo 6. Photo taken from the western location on August 16, 2018, facing West. This photo illustrates a bare patch with little to no desirable vegetation establishment. Additional reclamation activities will be required.

Inspection Photos
Location Name: COGGINS #10-34
API: 05-039-06608



Photo 7. Photo taken from the western perimeter of location on August 16, 2018, facing South. This photo illustrates little to no desirable vegetative establishment, mostly weedy, annual vegetation that needs to be controlled (e.g., mowed).

Inspection Photos
Location Name: COGGINS #10-34
API: 05-039-06608



Photo 8. Photo taken from a portion of access road to the location on August 16, 2018, facing South. This photo illustrates a bare patch with little to no desirable vegetation establishment. Additional reclamation activities will be required.

Inspection Photos
Location Name: COGGINS #10-34
API: 05-039-06608



Photo 9. Photo taken from the southern location on November 3, 2017, facing East.



Photo 10. Photo taken from the southern location on August 16, 2018, facing East. This photo illustrates a bare patch with little to no desirable vegetation establishment. Additional reclamation activities will be required.

Inspection Photos
Location Name: COGGINS #10-34
API: 05-039-06608



Photo 11. Photo taken from the northeastern perimeter of location on August 16, 2018. Fence repairs are needed to keep cattle out, as the surface owner grazes the adjacent lands.