

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Condition of area surrounding Chavez #1 well head upon arrival on 8/15/18.



Impacted soil remains underneath truck load out valve on AST.

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Weeds present across location as well as on and inside the secondary containment berm.



Rivas Earthworks beginning to excavate impacted soil from around the Chavez #1 well head.

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Excavation became wet at approximately 4' bgs.



Stained soil being loaded onto 12 cy dump truck.

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Material being removed from north side of well head.



Excavation of stained soil with infiltration of ground water.

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Extent of excavation on 8/15/18.



Open excavation around well head.