

Final Reclamation Inspection

August 21, 2018

Operator: PDC ENERGY INC - 69175

API: 05-123-14423

Inspection Document #: 682403891

Weld County, CO

NWSE Section 20 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SUCCO GAS UNIT #4-20
API: 05-123-14423



Aerial imagery from 1988 illustrates there was not a pre-existing road to the Succo Gas Unit.

Inspection Photos
Location Name: SUCCO GAS UNIT #4-20
API: 05-123-14423



Aerial imagery from 2017 illustrates the Succo Gas Unit during active operations. Access road and tank battery location have not been reclaimed per Rule 1004.

Inspection Photos
Location Name: SUCCO GAS UNIT #4-20
API: 05-123-14423



Photo 1. Photo taken from the tank battery location, facing South. Operator has failed to perform final reclamation activities at the tank battery and along the access road.



Photo 2. Photo taken from the western fill slope of the tank battery location, facing West. Photo illustrates rill erosion along the fill slope.

Inspection Photos
Location Name: SUCCO GAS UNIT #4-20
API: 05-123-14423



Photo 3. Photo taken from the well location, facing South. Well location will remain in-process as vegetation is not reflective of reference alfalfa areas. Bare soil patch was observed which may require the Operator to perform addition reclamation activities.



Photo 4. Reference area photo taken west of the well location, facing West.