

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/22/2018

Submitted Date:
08/22/2018

Document Number:
689801554

FIELD INSPECTION FORM

Loc ID 333336 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10323
Name of Operator: ENTEK GRB LLC
Address: 165 SOUTH UNION #366
City: LAKEWOOD State: CO Zip: 80228

Findings:

- 11 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
parsons, Kim		kparsons@entekenergy.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257908	WELL	SI	05/01/2016	GW	081-06988	MOFFAT COUNTY 26-12-89 1	SI
258037	WELL	SI	09/03/2013	DSPW	081-06995	MOFFAT 26-12-89 SWD #1	SI

General Comment:

[Routine UIC inspection.](#)

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery. Sign at each wellhead is the same.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/22/2018

Emergency Contact Number:			
Comment:	303-282-4933		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	1 - 2" steel riser at 40.97106, -107.35493 Flowline risers not LO/TO or marked are considered unused equipment.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/23/2018
Type	UNUSED EQUIPMENT		
Comment:	2 - 2" steel risers not marked for abandonment or LOTO at 40.97091, -107.35462 Flowline risers not LO/TO or marked are considered unused equipment.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/23/2018
Type	WEEDS		
Comment:	Noxious and annual weeds on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/05/2018

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		40.970910,-107.354620
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: No berm.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date: 09/24/2018

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 257908 Type: WELL API Number: 081-06988 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: No current MIT on record or delinquent as required by Rule 326. Last MIT 7/9/2013.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan. Date: 09/05/2018

Facility ID: 258037 Type: WELL API Number: 081-06995 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: MVRD
 TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 06/18/2014
 Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: Routine UIC inspection. Well shut-in at time of inspection.

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Culverts	Pass			
		Check Dams	Pass			Some check dams becoming full of sediment.
		Ditches	Pass			
Berms	Pass					
Gravel	Pass					
		Compaction	Pass			
Compaction	Pass					

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	258790	881907	
	268116	1121841	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689801558	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559353