

Inspection Photos

Location Name: Federal Goshawk - 68N60W / 28SWSW

Location #: 305200




Photo #1

Federal Goshawk 28-14 (API # 05-123-22634) wellhead

Sign is illegible

Bradenhead NOT plumbed to surface



Photo #2

Federal Goshawk 28-14, Fed Plover 28-5X,

Fed Toucan 28-14

Battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Goshawk - 68N60W / 28SWSW

Location #: 305200




Photo #3

***Federal Goshawk 28-14, Fed Plover 28-5X,
Fed Toucan 28-14***

Battery Sign is illegible



Photo #4

***Federal Goshawk 28-14, Fed Plover 28-5X,
Fed Toucan 28-14***

Oil Tanks – Rust, Poor paint condition



Inspection Photos

Location Name: Federal Goshawk - 68N60W / 28SWSW

Location #: 305200



Photo #5

Federal Goshawk 28-14 Access road

Road needs repaired



Photo #6

Federal Goshawk 28-14, Fed Plover 28-5X,

Fed Toucan 28-14

Branch roads need repaired



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Goshawk - 68N60W / 28SWSW

Location #: 305200



Colorado Oil & Gas Conservation Commission
40.62626, -104.10759, 1496.0m, 193°
2018/08/22 02:43:12 PM

Photo #7

***Federal Goshawk 28-14, Fed Plover 28-5X,
Fed Toucan 28-14***

Treater soil appears remediated



Colorado Oil & Gas Conservation Commission
40.62617, -104.10736, 1490.0m, 177°
2018/08/22 02:16:19 PM

Photo #8

***Federal Goshawk 28-14, Fed Plover 28-5X,
Fed Toucan 28-14***

Weeds on pit bank



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources