

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/22/2018

Submitted Date:

08/23/2018

Document Number:

687903055**FIELD INSPECTION FORM**Loc ID 308378 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Amato, Joseph	719-845-2110/719-859-2263	josephamato@tcenergy.us	All Inspections
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270571	WELL	PR	06/05/2004	GW	071-07944	APACHE CANYON 1-14	PR

General Comment:

Location

Lease Road:			
Type	Main		
comment:	Broken corrugated pipe near access lease road (photo)		
Corrective Action	Need to replace broken corrugated pipe.	Date:	09/23/2018
Type	Access		
comment:	Erosion and rutting on access lease road (Photo).		
Corrective Action	Need to address erosion and rutting on access lease road.	Date:	09/23/2018

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	
Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Pumphouse BLDG		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CALB - (3/21/18)		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	STEEL AST		,	
Comment:	1 - 15 bbl ST					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	STEEL AST		,	
Comment:	1 - 25 bbl ST					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	STEEL AST		,	

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	270571	Type:	WELL	API Number:	071-07944	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Fail					
Gravel	Pass	Gravel	Fail			

Comment: [Erosion and rutting on access lease road and broken corrugated pipe near access lease road \(Photos\).](#)

Corrective Action: [Address erosion, rutting and replace broken corrugated pipe.](#)

Date: 09/23/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
SEE : Lease road : Access. SEE : Stormwater : Erosion and rutting.	duranj	08/23/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687903056	Lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4560090
687903057	Well pad 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4560091
687903058	Well pad 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4560092
687903059	Well pad 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4560093
687903060	Erosion 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4560094
687903061	Broken culvert near access lease road	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4560095
687903062	Erosion 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4560096