

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/31/2018

Submitted Date:

08/24/2018

Document Number:

688800261**FIELD INSPECTION FORM**

Loc ID 324474 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Findings:**12 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone | Email                      | Comment                         |
|------------------|-------|----------------------------|---------------------------------|
| Inspections, All |       | inspection@sginterests.com | <a href="#">All Inspections</a> |
| Fischer, Alex    |       | alex.fischer@state.co.us   |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 276683      | WELL | PR     | 08/01/2012  | GW         | 051-06062 | MCINTYRE 11-90-14 1 | EI          |

**General Comment:**

On July 31, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests McIntyre 11-90-14 #1. For the most recent field inspection report of this facility, please refer to document #689401061.

| Location   |  |        |                 |
|--|--|--------|-----------------|
| <b>Lease Road:</b>                                     |  |        |                 |
| Type   | Access   |        |                 |
| comment:   |  |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                 |
| <b>Signs/Marker:</b>                                   |  |        |                 |
| Type   | CONTAINERS   |        |                 |
| Comment:   | Chemical injection system labeled and placarded.   |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type   | WELLHEAD   |        |                 |
| Comment:   | Sign mounted to stock panels around well head.   |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type   | TANK LABELS/PLACARDS   |        |                 |
| Comment:   | ASTs are labeled with capacity, contents, and NFPA placards.                                 |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Emergency Contact Number:                              |  |        |                 |
| Comment:   | Posted on location signs.  |        |                 |
| Corrective Action:                                     |  | Date:  | _____           |
| <b>Good Housekeeping:</b>                              |  |        |                 |
| Type   | STORAGE OF SUPL  |        |                 |
| Comment:   | Sections of poly water transfer line stored in NW corner of location during this inspection. |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                 |
| <b>Spills:</b>   |  |        |                 |
| Type   | Area   | Volume |                 |
| In Containment: No                                     |  |        |                 |
| Comment:   |  |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                 |
| <b>Fencing/:</b>                                       |  |        |                 |
| Type   | WELLHEAD   |        |                 |
| Comment:   | Stock panel enclosure.   |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type   | TANK BATTERY   |        |                 |
| Comment:   | Fencing around perimeter of battery and production equipment.                                |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| <b>Equipment:</b>                                      |  |        |                 |
| Type: Plunger Lift                                     | # 1  |        | corrective date |
| Comment:   |  |        |                 |

|                                   |                             |       |  |
|-----------------------------------|-----------------------------|-------|--|
| Corrective Action:                |                             | Date: |  |
| Type: Bird Protectors             | # 2                         |       |  |
| Comment:                          |                             |       |  |
| Corrective Action:                |                             | Date: |  |
| Type: Horizontal Heated Separator | # 1                         |       |  |
| Comment:                          |                             |       |  |
| Corrective Action:                |                             | Date: |  |
| Type: Ancillary equipment         | # 2                         |       |  |
| Comment:                          | Chemical injection systems. |       |  |
| Corrective Action:                |                             | Date: |  |
| Type: Gas Meter Run               | # 1                         |       |  |
| Comment:                          |                             |       |  |
| Corrective Action:                |                             | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type             | Tank ID | SE GPS                |
|--------------------|---|----------|------------------|---------|-----------------------|
| PRODUCED WATER     | 1 | 400 BBLs | HEATED STEEL AST |         | 39.099702,-107.419833 |
| Comment:           |   |          |                  |         |                       |
| Corrective Action: |   |          |                  |         | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CONDENSATE         | 1 | 400 BBLs | STEEL AST |         | 39.099795,-107.419922 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 276683 Type: WELL API Number: 051-06062 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment  |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|--|
| Gravel           | Pass            | Culverts                | Pass                  |  |                          |  |
| Compaction       | Pass            | Compaction              | Pass                  | Material Handling And Spill Prevention | Pass                     | Secondary containment for chemical containers. |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment  | User    | Date       |
|--|---------|------------|
| On July 31, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests McIntyre 11-90-14 #1. For the most recent field inspection report of this facility, please refer to document #689401061.<br>The location sign mounted to the stock panels around the well head is becoming illegible. Sections of the poly water transfer line were stored in the NW corner of the location during this inspection. | hughesj | 08/24/2018 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 688800262    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561582">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561582</a> |