

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/23/2018

Submitted Date:

08/24/2018

Document Number:

691200368

FIELD INSPECTION FORM

Loc ID 330786 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 14 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------------|---------------------------------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| , | | regulatory@foundationenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 251823 | WELL | SI | 02/01/2018 | OW | 123-19627 | HILL 31-9-11 | SI |

General Comment:

This is a WELL Inspection. Refer to FIR #691200366 for Battery details.

| Location | | | |
|--|---|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action: | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused pipe, fence, boards on N side of pump jack has been removed. This addresses the CA from FIR #684904362 dated 09/13/2017. | | |
| Corrective Action: | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | | | |
| Comment: | Refer to FIR #691200366 for additional fencing details. | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Iron mesh panel | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Other | # 1 | | corrective date |
| Comment: | Wellhead has master valve only which is closed. | | |
| Corrective Action: | | | Date: |
| Type: | # | | |
| Comment: | All other equipment has been removed from location. The battery is being abandoned. The 3 wells that are tied into this battery are being prepared to be P&A'd. | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 0 | | |

| | | | | |
|--------------------------|---|--|-------|--|
| Comment: | Stained soil at pump jack. Pump jack has been removed & stained soil appears to be remediated. This addresses the CA from FIR #684904362 dated 09/13/2017. | | | |
| Corrective Action: | | | Date: | |
| Type: Deadman # & Marked | # 4 | | | |
| Comment: | 4 / 4-marked | | | |
| Corrective Action: | | | Date: | |
| Type: Prime Mover | # 0 | | | |
| Comment: | Ajax Engine. Stained soil in engine house, around housing. Engine house & gas engine have been removed from location. Stained soil appears to be remediated. This addresses the CA from FIR #684904362 dated 09/13/2017. | | | |
| Corrective Action: | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|------|---------|-----------------------|
| | | | | | 40.611650,-104.131360 |
| Comment: | This abandoned battery previously serviced 3 locations when it had been active. (330622, 330786, 330787). Refer to FIR #691200366 for additional battery info. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 251823 Type: WELL API Number: 123-19627 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI. Records indicate SI since 2/2018.
This well is scheduled to be P&A'd according to Form 6 Doc #401600589 dated 4/17/2018.
Verbal notice of the P&A was provided by consultant Bud Rice indicating that P&A operations are planned to commence the week of 8/27/2018.

Corrective Action: Date:

BradenHead

Comment: Bradenhead appears plumbed to surface.
A bradenhead test was performed on 6/5/2018. Refer to Form 17 Doc #401741172.

Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 691200369 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561610 |