

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2018

Submitted Date:

08/24/2018

Document Number:

691200370**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 330787 Evins, Bret 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		regulatory@foundationenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159156	UIC DISPOSAL	AC	04/28/2006		-	HILL 31-14-7	SI
251824	WELL	SI	06/01/2017	DSPW	123-19628	HILL 31-14-7	SI

General Comment:[This is a UIC WELL Inspection. Refer to FIR #691200366 for Battery details.](#)

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron mesh panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type:	#		
Comment:	All other equipment has been removed from location. The battery is being abandoned. The 3 wells that are tied into this battery are being prepared to be P&A'd. Refer to FIR #691200366 for additional equipment info.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	4 / 4-marked		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead has master valve only which is closed.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
					40.611650,-104.131360	
Comment:	This abandoned battery previously serviced 3 locations when it had been active. (330622, 330786, 330787). Refer to FIR #691200366 for additional battery info.					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 159156 Type: UIC API Number: - Status: AC Insp. Status: SIFacility ID: 251824 Type: WELL API Number: 123-19628 Status: SI Insp. Status: SI**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: DSND

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 06/23/2016

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: This well is SI. SI since 6/2017.
 This well is scheduled to be P&A'd according to Form 6 Doc #401600593 dated 4/13/2018.
 Verbal notice of the P&A was provided by consultant Bud Rice indicating that P&A operations are planned to commence the week of 8/27/2018.

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI. SI since 6/2017.
 This well is scheduled to be P&A'd according to Form 6 Doc #401600593 dated 4/13/2018.
 Verbal notice of the P&A was provided by consultant Bud Rice indicating that P&A operations are planned to commence the week of 8/27/2018.

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead appears plumbed to surface.
 A bradenhead test was performed on 6/6/2018. Refer to Form 17 Doc #401741217.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200371	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561611