

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/24/2018

Submitted Date:

08/27/2018

Document Number:

679701030**FIELD INSPECTION FORM**

Loc ID 451015 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING, INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|---------------------|---------|
| Warner, Ryan | 970-669-6308 | magpieoil@yahoo.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|-----------------------------|-------------|
| 451017 | TANK BATTERY | AC | 06/09/2017 | | - | Hein & Hart #1 Tank Battery | EI |

General Comment:[COGCC Inspection of produced water vessel removal - Remediation #11686](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment: [At Battery](#)

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| Type | Area | Volume |
|------|------|--------|
| | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

Comment:

Corrective Action:

Date:

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--|---|----------|------|---------|--------|
| PRODUCED WATER | 0 | | | | , |
| Comment: Produced water vessel removed - Remediation 11686 | | | | | |
| Corrective Action: | | | | | Date: |

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

| <u>Berms</u> | | | | |
|---|----------|---------------------|---------------------|------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Insufficient | | Inadequate |
| Comment: Burrow in containment berm & berm worn at loadout. | | | | |
| Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4). | | | | Date: 09/26/2018 |
| <u>Venting:</u> | | | | |
| Yes/No | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| <u>Flaring:</u> | | | | |
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Environmental**Spill/Remediation:**

Comment: COGCC inspection fo Remediation# for removal of produced water tank. Open excavation present. Soil stockpile adjacent excavation. Operator has submitted results of soil sampling from excavation via Form 27 Supplemental Report in reference to Remediation #11686

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------------------------|---|
| 679701032 | Hein Hart 1 field Photos 8-24-2018 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4562686 |