

Well Name: Jaquez 5F, Jaquez # 9 **API #** 05-67-07693 05-067-10021
Inspection Number: 680602788
Inspection Number: 685305072
Corrective Action: Storm water controls such as silt traps, armoring, check dams need to be installed
Corrective Action: Waddles are not properly trenched, diversion ditched was breeched and filled to 75%-85% with silt.

Correction Action Due: 8/4/2018
Action Completed: 8/3/2018
Action Taken: Installed silt traps, armored culverts, installed check dams along road side ditches.
Action Taken: Retrenched waddles, cleaned and reset others, repaired and cleaned out diversion ditch, cleaned repaired and reinforced rock rundown in NE corner of location.



