

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2018

Submitted Date:

08/27/2018

Document Number:

689301832

**FIELD INSPECTION FORM**

Loc ID 421392 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
 OGCC Operator Number: 10456  
 Name of Operator: CAERUS PICEANCE LLC  
 Address: 1001 17TH STREET #1600  
 City: DENVER State: CO Zip: 80202

**Findings:**  
13 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerusoilandgas.com	<a href="#">all Piceance inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301754	WELL	PR	06/21/2011	GW	045-18257	ENCANA FEE 3-16 (A10E)	PR
301755	WELL	PR	07/01/2011	GW	045-18258	ENCANA FEE 2-13C (A10E)	PR
421401	WELL	PR	10/01/2017	GW	045-20395	EnCana Fee 10-2D (A10E)	PR

**General Comment:**  
[Routine Field Inspection](#)

Location						
<b>Lease Road:</b>						
	Type	Access				
	comment:					
	Corrective Action	L		Date:		
Overall Good: <input checked="" type="checkbox"/>						
Emergency Contact Number:						
	Comment:	1-800-791-7691				
	Corrective Action:			Date:		
<b>Good Housekeeping:</b>						
	Type	WEEDS				
	Comment:	Weeds on location near wellheads and Tanks, see photos				
	Corrective Action:	Comply with Rule 603.f .			Date:	09/06/2018
Overall Good: <input type="checkbox"/>						
<b>Spills:</b>						
	Type	Area	Volume			
In Containment: No						
	Comment:					
<input type="checkbox"/> Multiple Spills and Releases?						
<b>Fencing/:</b>						
	Type	SEPARATOR				
	Comment:	Concrete barriers.				
	Corrective Action:			Date:		
	Type	WELLHEAD				
	Comment:	Livestock gates				
	Corrective Action:			Date:		
<b>Equipment:</b>						
					corrective date	
Type:	Ancillary equipment	# 1				
	Comment:	Chemical unit at wellheads				
	Corrective Action:			Date:		
Type:	Plunger Lift	# 3				
	Comment:					
	Corrective Action:			Date:		
Type:	Gas Meter Run	# 1				
	Comment:					
	Corrective Action:			Date:		
Type:	Emission Control Device	# 1				
	Comment:					
	Corrective Action:			Date:		

Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	100 BBLs	Open Top		,
Comment:	Stained ground by corner on 110 bbl blowdown tank, see photo				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 09/27/2018

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	500 BBLs	HEATED STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES		
Comment:	Bradenheads venting to tank blowdown tank.		
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 301754 Type: WELL API Number: 045-18257 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 301755 Type: WELL API Number: 045-18258 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 421401 Type: WELL API Number: 045-20395 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Berms						
				Material Handling And Spill Prevention		
Ditches						
Seeding						
		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301833	Inspection photo 689301833	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4563272">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4563272</a>