

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2018

Submitted Date:

08/27/2018

Document Number:

675001058

FIELD INSPECTION FORM

Loc ID 332563 Inspector Name: Duran, Alicia On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------|
| | | NBL_DJBU_Inspections@NB LENERGY.COM | |

General Comment:

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|-----------------------------------|-------|--|
| Type | SEPARATOR | | |
| Comment: | Livestock | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Metal berm with concrete barriers | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | | | corrective date |
|-----------------------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |

| | | |
|---|--|-------|
| Comment: Automation array | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------------------------|---|-----------|-------------|---------|--------|
| PRODUCED WATER | 1 | <100 BBLs | BV CONCRETE | | |
| Comment: 53 BBLs | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|---|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: Shared berm with crude oil tank. | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|-----------------------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 40.333860,-104.527740 |
| Comment: Anchored | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | | | |
|------------------|----------|--|--|--|--|
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | | |
|--------------------|----|--|--|-------|
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Flaring:

| | | | | |
|--------------------|--|--|--|-------|
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------------|---|
| 675001059 | photos of completed CA | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4563343 |
| 675001060 | Photos before CA | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4563344 |