

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2018

Submitted Date:

08/28/2018

Document Number:

679701035**FIELD INSPECTION FORM**
 Loc ID 420661 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10629Name of Operator: FIFTH CREEK ENERGY OPERATING COMPANY LLCAddress: 5251 DTC PKWY STE 420City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Singer, Sheila		ssinger@hpres.com	
Barber, Matt		mbarber@hpres.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420664	WELL	PR	05/25/2012	OW	123-32661	GARDEN CREEK 16-2314H	EI
456897	SPILL OR RELEASE	AC			-	Produce water tank leak (GardenCrk) 16-2314H	EI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLS	STEEL AST		,	
Comment: corrosion hole in base of tank						
Corrective Action: isolate tank and repair/replace tank						Date: 09/27/2018

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	YES		
Comment:	Audible venting from corrosion hole in produced water tank, confirmed with 4-gas meter. Operator verbally notified on 8/28/2018 11:00 a.m.		
Corrective Action:	Isolate tank to control venting	Date:	08/29/2018

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	420664	Type:	WELL	API Number:	123-32661	Status:	PR	Insp. Status:	EI
Facility ID:	456897	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Spill/Remediation:**Comment: [Spill from produced water tank reported by Operator, Form 19 Initial/Supplemental Received](#)Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679701036	Garden Creek 16-1314H Photos 8-28-18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4564393