

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/22/2018

Submitted Date:

08/22/2018

Document Number:

689801556

**FIELD INSPECTION FORM**

Loc ID 313115 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10323  
Name of Operator: ENTEK GRB LLC  
Address: 165 SOUTH UNION #366  
City: LAKEWOOD State: CO Zip: 80228

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
parsons, Kim		kparsons@entekenergy.com	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257945	WELL	SI	01/27/2016	GW	081-06989	MOFFAT 23-12-89 2	SI

**General Comment:**

[Routine FIU inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wellhead sign has been knocked over.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	303-282-4933	Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Annual weeds on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/05/2018

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 257945 Type: WELL API Number: 081-06989 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No current MIT on record or delinquent as required by Rule 326.  
Last MIT was 7/9/2013.

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan. Date: 09/05/2018

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Gravel	Pass			
Gravel	Pass					
		Check Dams	Pass			Some check dams becoming sediment logged.
		Compaction	Pass			
		Culverts	Pass			
Compaction	Pass					

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401741407	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559362">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559362</a>
689801560	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559355">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559355</a>