

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/22/2018

Submitted Date:

08/22/2018

Document Number:

691200358

**FIELD INSPECTION FORM**

Loc ID 331151 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

- 17 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Peter Cowan		picowan@blm.gov	<a href="#">BLM; federal/federal inspections</a>
		vkoehler@fs.fed.us	<a href="#">USFS; federal/federal inspections</a>
		regulatory@foundationenergy.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258930	WELL	PR	06/28/2001	GW	123-20234	FEDERAL TOUCAN 28-14	PR

**General Comment:**

[This is a WELL Inspection. For Battery Inspection info refer to FIR #691200356.](#)

Location				
<b>Lease Road:</b>				
	Type	Access		
	comment:	Adequate		
	Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
	Type	WELLHEAD		
	Comment:	Sign label is faded or peeling. Signs and Markers General Condition. Sign not legible. Install sign to comply with Rule 210.e.		
	Corrective Action:	Comply with Rule 210.e.		Date: 10/22/2018
<b>Emergency Contact Number:</b>				
	Comment:	<input style="width: 100%;" type="text"/>		
	Corrective Action:	<input style="width: 100%;" type="text"/>		
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No <input type="checkbox"/>				
	Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
	Type	PUMP JACK		
	Comment:	Iron mesh panel		
	Corrective Action:			Date:
	Type	WELLHEAD		
	Comment:	Barbed wire		
	Corrective Action:			Date:
<b>Equipment:</b>				
				corrective date
Type:	Prime Mover	# 1		
	Comment:	Gas Engine. Stained soil in engine house appears to have been remediated addressing the CA form FIR #684903928 dated 7/27/2017.		
	Corrective Action:			Date:
Type:	Pump Jack	# 1		
	Comment:	Stained soil at wellhead appears to have been remediated addressing the CA form FIR #684903928 dated 7/27/2017.		
	Corrective Action:			Date:
Type:	Deadman # & Marked	# 4		
	Comment:	3 / 4. 1 anchor is bent over and unmarked. Mark guy line anchors per Rule 604.c.(2)Q. Any CA(s) form previous FIRs that have not been addressed are still applicable. The original CA date still applies.		
	Corrective Action:	Comply with Rule 604.c.(2)Q.		Date: 08/04/2017

Type:	#		
Comment:	Refer to FIR #691200356 for additional equipment details.		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	At wellhead. Has drip tray.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.626209,-104.107827
Comment:	This centralized battery services 3 locations (305200, 331082, 331151). Refer to FIR #691200356 for Tanks & Berms details.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 258930 Type: WELL API Number: 123-20234 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR.

Corrective Action:

Date:

**BradenHead**

Comment: Bradenhead appears plumbed to surface.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
-------	--------	---------	------	-------

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: [Refer to FIR #691200356 for pit information.](#)

Corrective Action

Date:   

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401741424	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559385">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559385</a>
691200359	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559383">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559383</a>