

Inspection Photos
Location Name: Pinnacle Unit 10-30
API: 05-103-08459



Photo 1. Overview of location taken at entrance facing southwest.

Inspection Photos
Location Name: Pinnacle Unit 10-30
API: 05-103-08459



Photo 2. Incomplete tank labels.



Photo 3. No wildlife protection apparent on exhaust on right hand tank.

Inspection Photos
Location Name: Pinnacle Unit 10-30
API: 05-103-08459



Photo 4. Example of blooming noxious weeds on location.



Photo 5. Stained soil at wellhead.

Inspection Photos
Location Name: Pinnacle Unit 10-30
API: 05-103-08459



Photo 6. Stained soil at pump jack exhaust.



Photo 7. Stained soil at tank base.

Inspection Photos
Location Name: Pinnacle Unit 10-30
API: 05-103-08459



Photo 8. Stained soil at tank base.



Photo 9. Stained soil at tank base.

Inspection Photos
Location Name: Pinnacle Unit 10-30
API: 05-103-08459



Photo 10. Photo of active leak location in line from wellhead separator.



Photo 11. Pit. 2 feet of freeboard not present on left hand bank.

Inspection Photos
Location Name: Pinnacle Unit 10-30
API: 05-103-08459



Photo 12. Oil in pit.



Photo 13. Oil and oil saturated absorbent pads and sheen in pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 689801591