

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/21/2018

Submitted Date:

08/21/2018

Document Number:

689701736

**FIELD INSPECTION FORM**

Loc ID 334929 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210750	WELL	PR	04/20/1986	GW	045-06508	MOBIL W-7-34	PR
210906	WELL	PR	07/06/1990	GW	045-06664	MOBIL GV 41-34	PR
265748	WELL	PR	04/27/2003	OW	045-09055	PA 314-34	PR
271262	WELL	PR	03/03/2005	GW	045-09855	PA 311-3	PR
271263	WELL	PR	01/28/2005	GW	045-09854	PA 414-34	PR

**General Comment:**

[Follow up inspection 689701547](#)  
[Corrective action not completed.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well signs are discolored on PA 414-34, GV 41-34, PA 314-34, W-7-34		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds around around W 7-34. Dead weed debris around location.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/31/2018
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment around W 7-34. Unused fence post from previous inspection has not been remove. Additional material found, strands on barb wire and metal brace with bolts.		
Corrective Action:	Comply with Rule 603.f	Date:	07/30/2018

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	210750	Type:	WELL	API Number:	045-06508	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:								Date:	
Facility ID:	210906	Type:	WELL	API Number:	045-06664	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:								Date:	
Facility ID:	265748	Type:	WELL	API Number:	045-09055	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:								Date:	
Facility ID:	271262	Type:	WELL	API Number:	045-09855	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:								Date:	
Facility ID:	271263	Type:	WELL	API Number:	045-09854	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:								Date:	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401741587	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559524">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559524</a>
689701737	Inspection 689701736 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559521">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559521</a>