

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

Equipment:

					corrective date
Type:	Plunger Lift	# 2			
Comment:					
Corrective Action:			Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Shared at location number: 425656				
Corrective Action:				Date:	

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 246384 Type: WELL API Number: 123-14181 Status: PA Insp. Status: PA

Cement

Cement Contractor
 Contractor Name: _____ Contractor Phone: _____

Surface Casing
 Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing
 Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing
 Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations
 Depth Plugs(feet range): _____ Cement Volume (sx): _____
 Good Return During Job: _____ Cement Type: _____

Comment: Well has been plugged. Two active wells remain on location at time of inspection.

Corrective Action: _____ Date: _____

Facility ID: 425617 Type: WELL API Number: 123-34450 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead plumbed to surface.

Corrective Action: _____ Date: _____

Facility ID: 425721 Type: WELL API Number: 123-34494 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead plumbed to surface.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine inspection.	carlilec	08/30/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690002335	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4566737