

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2018

Submitted Date:

08/30/2018

Document Number:

688302414**FIELD INSPECTION FORM**Loc ID 451166 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: 600 N DAIRY ASHFORD RDCity: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|-----------------------------------|------------------------|
| ConocoPhillips | | COPColoradoReg@conocophillips.com | |
| Yu, Liang | 281-467-5712 | Liang.Yu@conocophillips.com | Regulatory Coordinator |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 451167 | WELL | DG | 03/02/2018 | | 001-10073 | Big Sandy 3-65 36-31 2CH | WO |
| 453493 | WELL | DG | 03/01/2018 | | 001-10101 | Big Sandy 3-65 36-31 2AH | WO |

General Comment:

Reinspection. All corrective actions from inspection #688301834 were completed: Form 19I and 19S were submitted, weeds mowed and it was discussed that the valve at the knock out was not malfunctioning at the time of the spill and needed no repairs.

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 855-595-8258

Corrective Action: _____ Date: _____

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | barbed wire | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 451167 Type: WELL API Number: 001-10073 Status: DG Insp. Status: WOFacility ID: 453493 Type: WELL API Number: 001-10101 Status: DG Insp. Status: WO**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 688302417 | Burlington Big Sandy 3-65 36-31 2AH Reinspection | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4566905 |