

Inspection Photos
Location Name: Entrada 1-28
API: 05-057-06116



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. Noxious and annual weeds outside wellhead housing; rods, wood and other debris to the left.