

Inspection Photos

Operator: Logos Operating

API: 05-067-05180

Date: 8/16/2018



Photo 1. View of the project area from the southwestern corner facing center. What appears to be surface owner debris is stored south of facilities. If this is on well pad disturbance it needs to be removed.



Photo 2. View of Russian knapweeds (*Acroptilon repens*) within the southern project area. Thousands of individuals are present within the interim reclamation area.



Photo 3. View of rilling in the southeastern portion of the interim reclamation area. Small plants are largely R. knapweeds.



Photo 4. View of wire debris and erosional channel forming at the culvert outlet in the northeastern portion of the project area.



Photo 5. View of the northern and northeastern cut-slopes from the northeastern edge facing northwestward. Vegetation is sparse on the cut-slope and erosion is occurring in several areas.



Photo 6. View of erosional channel and sediment deposition in the northeastern project area.



Photo 7. View of erosion occurring in the northwestern corner of the project area. Wattles do not appear to be functioning and are not sufficient stormwater controls for the slope.



Photo 8. View of debris in the western project area.