

Inspection Photos  
Location Name: Schroeder 33-32  
API: 05-081-07131



**Photo 1. Overview of location taken at entrance facing west.**

Inspection Photos  
Location Name: Schroeder 33-32  
API: 05-081-07131



**Photo 2. Stained soil at separator.**



**Photo 3. Stained soil at separator.**

Inspection Photos  
Location Name: Schroeder 33-32  
API: 05-081-07131



**Photo 4. Unmarked risers.**



**Photo 5. Unmarked risers. Equipment stored on location.**



Inspection Photos  
Location Name: Schroeder 33-32  
API: 05-081-07131



**Photo 6. Unmarked riser. Equipment stored on location.**



**Photo 7. Unmarked risers. Equipment stored on location.**

Inspection Photos  
Location Name: Schroeder 33-32  
API: 05-081-07131



**Photo 8. Unmarked risers. Equipment stored on location.**



**Photo 9. Stained soil at wellhead.**



Inspection Photos  
Location Name: Schroeder 33-32  
API: 05-081-07131



**Photo 10. Equipment stored on location.**



**Photo 11. Equipment stored on location.**

Inspection Photos  
Location Name: Schroeder 33-32  
API: 05-081-07131



**Photo 12. Equipment stored on location.**



**Photo 13. Equipment stored on location.**

Inspection Photos  
Location Name: Schroeder 33-32  
API: 05-081-07131



**Photo 14. Equipment stored on location.**



**Photo 15. Equipment stored on location.**



Inspection Photos  
Location Name: Schroeder 33-32  
API: 05-081-07131



**Photo 16. Equipment stored on location.**



**Photo 17. Equipment stored on location.**

Inspection Photos  
Location Name: Schroeder 33-32  
API: 05-081-07131



**Photo 18. Equipment stored on location.**



**Photo 19. Equipment stored on location.**