

Inspection Photos

Operator: BP America

API: 05-067-08808

Date: 8/16/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western portion of the project area from the northwestern corner facing southward.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4. View of erosional channel in the northeastern project area that needs stabilization.



Photo 5. View of pedestaling around vegetation and sediment movement in sheet flow and rilling pattern along the eastern edge of the project area. Sediment is being deposited offsite.



Photo 6. View of kochia (*Kochia scoparia*) that will soon dry and become debris on the access road.



Photo 7. View of Russian knapweeds (*Rhaponticum repens*) within the northwestern portion of the project area.