

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/29/2018

Submitted Date:
09/04/2018

Document Number:
685305271

FIELD INSPECTION FORM

Loc ID 325547 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 35720
Name of Operator: GREER* JAMES R & NATALIE
Address: 7882 CO RD 100
City: HESPERUS State: CO Zip: 81326

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|-----------------------------|---------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Labowskie, Steve | | steve.labowskie@state.co.us | COGCC |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 214982 | WELL | DM | 01/07/1987 | GW | 067-06587 | KENNEDY 1 | PR |

General Comment:

Inspection completed as follow-up inspection requirement.
This inspection does not alleviate requirement for operator to complete any open corrective actions from previous inspections.
See link at end of report for path to downloadable pictures.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|------------|
| Type | WELLHEAD | | |
| Comment: | No wellhead sign at location. Similiar issue noted in previous inspection 685300614. Corrective action required by inspection report document number 685304920 not completed. Corrective action date remains the same to document days of noncompliance. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 07/16/2018 |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|------------|
| Comment: | No contact information posted at wellhead. Similiar issue noted in previous inspection 685300614. Corrective action required by inspection report document number 685304920 not completed. Corrective action date remains the same to document days of noncompliance. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 07/13/2018 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| | | | |
|---------------------------|---|-------|-----------------|
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | Wellhead. Well appears to possibly have a below grade leak with fluids and gas migrating to the surface around wellhead. Corrective action required by inspection report document number 685304920 not completed. Corrective action date remains the same to document days of noncompliance. | | |
| Corrective Action: | Excavate around wellhead to determine source of leak per Rule 605.d. "Identify and repair to comply with Rules 605.d. Contact inspection staff if bradenhead access is found and schedule a witnessed BH test using COGCC Bradenhead Testing and Reporting Procedure. | Date: | 07/13/2018 |

Venting:

| | | | |
|--------------------|---|-------|--|
| Yes/No | YES | | |
| Comment: | Visible gas release (bubbling) through fluids in wellhead cellar. | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 214982 Type: WELL API Number: 067-06587 Status: DM Insp. Status: PR

COGCC Comments

| Comment | User | Date |
|--|---------|------------|
| At the time of folow-up inspection the wellhead cellar had standing fluid surrounding wellhead and bubbles streaming to the surface around wellhead casing and in several places inside cellar area. Unknown volume. Similiar issues were identified in previous inspection 685300614 and 685304920. No corrective actions required by inspection document number 685304920 have been completed. | stjohnw | 09/04/2018 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------------|---|
| 685305305 | Wellhead video previous inspection. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4570333 |
| 685305306 | Wellhead video current inspection. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4570334 |
| 685305307 | Inspection photos. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4570335 |