

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2018

Submitted Date:

09/05/2018

Document Number:

688800269**FIELD INSPECTION FORM**
 Loc ID 325935 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215590	WELL	PR	10/25/1989	GW	067-07195	STREETER B 1	EI
457125	SPILL OR RELEASE	AC			-	SPILL/RELEASE POINT	EI

General Comment:

On August 24, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Streeter B #1. For the most recent field inspection report of this facility, please refer to document #680601799. This site visit was in response to Spill/Release Point ID #457125, discovered on 8/23/18. For more information regarding this release of produced water, please refer to Initial Spill/Release report document #401744320.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Stock panel enclosures around separator and meter run.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Stock panel enclosure around well head.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry.		
Corrective Action:		Date:	

Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>215590</u>	Type:	<u>WELL</u>	API Number:	<u>067-07195</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>457125</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 40

Comment: [Please refer to document #401744320 for more information regarding this release.](#)Corrective Action: [Submit a Form 27 Site Investigation and Remediation Workplan, per Rule 906.c.](#)

Date: 10/05/2018

Reportable: YES

GPS: Lat 37.270137

Long -107.626962

Proximity to Surface Water: 6680

Depth to Ground Water: 55

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 24, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Streeter B #1. For the most recent field inspection report of this facility, please refer to document #680601799. This site visit was in response to Spill/Release Point ID #457125, discovered on 8/23/18. For more information regarding this release of produced water, please refer to Initial Spill/Release report document #401744320. Underground utilities had just been marked in preparation for excavating the damaged water gathering line. An approximately 2' by 3' hole existed near the meter run where it appeared that water day lighted. The area was wet and evidence of sample collection remained.	hughesj	09/05/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800270	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4570368