

Inspection Photos

Operator: Logos Operating

API: 05-067-08097

Date: 8/16/2018



Photo 1. View of the project area from the western corner facing center.



Photo 2. View of the western portion of the project area from the western corner facing southeastward.



Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is sparse on the fill slope. Many grasses appear to be dried out.



Photo 4. View of Canada thistles (*Cirsium arvense*) within the southern project area.



Photo 5. View of erosional channels and sediment deposition within the northwestern cut-slope.



Photo 6. View of the northern portion of the project area from the northwestern corner facing eastward. Erosional channels and sediment deposition is occurring within this portion of the project area.



Photo 7. View of the southern and southwestern cut-slope from the southern edge facing westward. Erosion is occurring in this portion of the cut-slope near the top where vegetation is not established.