

# Inspection Photos

Operator: BP America

API: 05-067-06998

Date: 8/16/2018



**Photo 1. View of the project area from the southern edge facing center. Revegetation is progressing within the southern project area.**



**Photo 2. View of the western corner of the project area from the northwestern corner facing southward.**



**Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward.**



**Photo 4. View of musk thistles (*Carduus nutans*) in flower and seed condition in the eastern project area.**