

Inspection Photos
Location Name: Moyer - 612N56W / 29SESE
Location #: 317529



Photo #1
Moyer Unit 16-29 (API 05-123-07014) wellhead
Stained soil
From previous FIR



Photo #2
Moyer Unit 16-29 wellhead
Stained soil appears to be remediated
Bradenhead needs plumbed to surface

Inspection Photos
Location Name: Moyer - 612N56W / 29SESE
Location #: 317529



Photo #3
Moyer Unit 16-29 wellsite sign



Photo #4
Moyer Unit Battery
Free Water Knockout

Inspection Photos

Location Name: Moyer - 612N56W / 29SESE

Location #: 317529



Photo #5

Moyer Unit Battery

Moyer 11-29, 13-29, 15-29, 3-32, 11-32 (UIC wells)

Moyer 10-29, 14-29, 16-29, 15-30, 16-30, 6-32

(Producing wells)



Photo #6

Moyer Unit H2O tanks



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources