

Inspection Photos

Operator: BP America

API: 05-067-07014

Date: 8/21/2018



Photo 1. View of the project area from the southern edge facing center.



Photo 2. View of the eastern corner of the project area from the southeastern corner facing northward. Revegetation is sparse on fill slopes.



Photo 3. View of the southern project area and adjacent irrigation ditch.



Photo 4. View of musk thistles (*Carduus nutans*) in flower and seed condition in the northeastern project area.