

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/05/2018

Submitted Date:

09/07/2018

Document Number:

693700005**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------------|-------|--|---------------------------------|
| Inspections, General | | sandridgeenvironmental@sandridgeenergy.com | All Inspections |
| Leonard, Mike | | mike.leonard@state.co.us | |
| Axelson, John | | john.axelson@state.co.us | |
| Morton, Marc | | marc.morton@state.co.us | |
| Deranleau, Greg | | greg.deranleau@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|-------------------------|-------------|
| 456513 | SPILL OR RELEASE | AC | 08/28/2018 | | - | 9552 Poudre Canyon Road | EI |

General Comment:[COGCC Environmental Inspection - Poudre Canyon Spill](#)

Environmental**Waste Management:**

| Type | Management | Condition | GPS (Lat) | (Long) |
|-------------------|---|-----------|-----------|--------|
| Oily Soil | Piles | Adequate | | |
| Comment | 50-60 yards of excavated/impacted soil is stockpiled beneath plastic sheeting, pending next day haul for disposal | | | |
| Corrective Action | | | | Date: |

Spill/Remediation:

| | | | | |
|--------------------|--|--|--|-------|
| Comment: | Custom Environmental excavated and stockpiled 50-60 yards of material from the shoulder of the Highway in the area of the crash and spill. Remaining material appears to be a mixture of soil, road based, and recycled asphalt. Parts of the westernmost spill area and release point were excavated to a layer of intact asphalt. Sandridge soil collected 5 soil samples from the excavated area. COGCC collected one split sample from adjacent Sandridge sample point 02. | | | |
| Corrective Action: | | | | Date: |

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 693700011 | Site Photos 9-5-2018 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573103 |