

Inspection Photos
Location Name: Ellgen 11-10-1
API: 05-081-07666



Photo 1. Long distance overview of location taken from lease road facing northeast.



Photo 2. Overview of location taken at entrance facing north.

Inspection Photos
Location Name: Ellgen 11-10-1
API: 05-081-07666



Photo 3. Photo of back pressure control valve. Area of failure is in top gasket/seal where black staining is.



Photo 4. Photo of line valve was removed from, black line in back flowline has been added since valve was removed.

Inspection Photos
Location Name: Ellgen 11-10-1
API: 05-081-07666



Photo 5. Area of ignition and spread of fire.



Photo 6. Stained soil and gravel at base of combustor/flowlines where fire was ignited.