

Inspection Photos

Operator: Merrion Oil and Gas

API: 05-067-09391

Date: 8/21/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 3. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing within the interim reclamation areas.



Photo 4. View of kochia (*Kochia scoparia*) weeds growing around fired equipment that need management.



Photo 5. View of erosion and sediment deposition along the access road that needs to be repaired, facing southeastward.