

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/07/2018

Submitted Date:

09/10/2018

Document Number:

688800277**FIELD INSPECTION FORM**Loc ID 306890 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274089	WELL	PR	10/12/2004	GW	067-08982	DWIGHT SOSSAMAN A 2	EI

General Comment:

On September 7, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Dwight Sossaman A #2. For the most recent field inspection report of this facility, please refer to document #680600030.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign mounted to perimeter fencing near entrance to location.			
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:	Free standing sign near PBV. Label and placard also directly on tank.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Lube Oil	WELLHEAD	<= 1 bbl		
Comment:	Stained gravel beneath pump on well head. Area of stained gravel leading away from well head also.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 10/10/2018
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Stock panel fencing.			
Corrective Action:			Date:	
Type	LOCATION			
Comment:	Perimeter fencing.			
Corrective Action:			Date:	
Equipment:				
Type: Progressive Cavity	# 1			corrective date
Comment:	Stained soil beneath pump. Equipment is tagged out with "No Pump Action".			
Corrective Action:				Date:
Type: Vertical Heated Separator	# 1			
Comment:				
Corrective Action:				Date:

Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical service equipment		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.246440,-107.603379	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
		Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On September 7, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Dwight Sossaman A #2. For the most recent field inspection report of this facility, please refer to document #680600030. A swath leading from the well head to the outside of the stock panel enclosure is stained with oil. The area below the progressive cavity pump is also stained with oil. The well and associated equipment was tagged out at the time of this inspection.	hughesj	09/10/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800278	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4574274