

Inspection Photos
Location Name: Keating #2
API: 05-067-09001



Sign holder is broken, sign is becoming illegible.



Stained soil near pump jack.

Inspection Photos
Location Name: Keating #2
API: 05-067-09001



Lube oil container on secondary containment.



Keating #2 location photo.