

Inspection Photos

Operator: Logos Operating

API: 05-067-09055

Date: 9/10/2018



Photo 1. View of the project area from the northwestern corner of the working area facing center.



Photo 2. View of the northwestern portion of the project area from the northern edge facing westward. Revegetation is progressing with grasses, forbs, and shrubs such as blue grama (*Bouteloua gracilis*), snakeweed (*Gutierrezia sarothrae*), and fourwing saltbush (*Atriplex canescens*).



Photo 3. View of the western portion of the project area from the northern edge facing southward.



Photo 4. View of the southern fill slope from the southwestern edge facing eastward. Some rilling is occurring here as vegetation is more sparse on the slope.



Photo 5. View of marked rig anchor within the southern project area.