

Inspection Photos

Operator: BP Production

API: 05-067-07589

Date: 9/10/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is sparse, but appears to be progressing in portions of the project area. This should be monitored.





Photo 3. View of the western portion of the project area from the northwestern corner facing southward.