

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/04/2018

Submitted Date:

09/05/2018

Document Number:

691200407

FIELD INSPECTION FORM

Loc ID 317532 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 7800
Name of Operator: BEREN CORPORATION
Address: 2020 N BRAMBLEWOOD STREET
City: WICHITA State: KS Zip: 67206

Findings:

- 27 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Gul, Awais		gula@berexco.com	
Hanes, Shawn		haness@berexco.com	
Reynolds, Rodney	(316) 337-8340	reynoldsr@berexco.com	AI inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100573	PIT	AC	09/23/1999		-	MOYER "A"	AC
100574	PIT	AC	09/23/1999		-	MOYER "A"	AC
100575	PIT	AC	09/23/1999		-	MOYER "A" 1	AC
239238	WELL	PR	07/29/2014	OW	123-07025	MOYER UNIT 14-29	PR
433344	TANK BATTERY	AC	04/14/2009		-	MOYER 'A'-612N56W 29SESW	AC

General Comment:

[This is a WELL & BATTERY Inspection. Follow-up to FIR #684905482 dated 6/1/2018.](#)

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil at valve fittings, around vessels, in treater house, see pictures. Refer to rule 603.f. Properly treat or dispose of oily waste in accordance with Rule 907.e. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. This CA was referenced in FIR# 684905482 dated 6/1/2018. The original CA date remains applicable.		
Corrective Action:	Comply with Rules 603.f, 605.d, & 907.e.	Date:	<u>07/02/2018</u>
Type	TRASH		
Comment:	Trash in separator, knockout, injection pumphouse house. This CA was referenced in FIR# 684905482 dated 6/1/2018. The original CA date remains applicable.		
Corrective Action:	Comply with rule 603.f.	Date:	<u>07/03/2017</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	

In Containment: No

Comment:


Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Iron mesh panel		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Iron rod fence		
Corrective Action:			Date:
Type	PIT		
Comment:	Iron mesh panel		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron mesh panel		
Corrective Action:			Date:

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	1.) Electric motor drives pump jack. 2.) Electric motor drives triplex injection pump.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	At well: 1 - chem. pump / drum w/ drip tray 1 - drum to bleed fluid		
Corrective Action:			Date:
Type: Ancillary equipment	# 7		
Comment:	7 - chemical pumps w/ drums/tanks & drip trays.		
Corrective Action:			Date:
Type: FWKO	# 1		
Comment:	140 Bbls. capacity		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	4/4-marked.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	1.) Triplex injection pump to inject into injection wells.		
Corrective Action:			Date:

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY			
Comment: This centralized battery serves 14 locations (317535, 405727, 317531, 317533, 317536, 317528, 317530, 317532, 317529, 317526, 317525, 317534, 317538, 317537). Refer also to Tank Battery Facility ID #433344.						
Corrective Action:					Date:	
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		40.980504,-103.661013	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Shares berms with 6 - 300 Bbls. produced H2O tanks & FWKO.						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	400 BBLs	FIBERGLASS AST		40.980338,-103.661201	
Comment: Used as a gunbarrel skimming tank.						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)	Produced H2O / Crude Oil					
Other (Capacity)						
Other (Type)						
<u>Berms</u>						

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms with 5 - Produced oil tanks.					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLs	STEEL AST		40.980338,-103.661201
Comment:					
Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms with 400 Bbls. Produced oil / H2O Gunbarrel skimming tank.					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	6	300 BBLs	FIBERGLASS AST		40.980504,-103.661013
Comment:					
Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms with 200 Bbls. produced H2O tank & FWKO.					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:



Inspected Facilities

Facility ID: 100573 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 100574 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 100575 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 239238 Type: WELL API Number: 123-07025 Status: PR Insp. Status: PR

Facility ID: 433344 Type: TANK API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: PR.

Corrective Action:

Date:

BradenHead

Comment: Bradenhead is NOT plumbed to surface. Foreman advised they will have bradenhead plumbed before the end of SEP 2018.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: [Stormwater erosion has been addressed. This CA was referenced in FIR# 684905482 dated 6/1/2018.](#)

Corrective Action: _____ Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Emergency Lined: _____ Pit ID: 100574 Lat: 40.979862 Long: -103.660615

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____ Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective Action _____ Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action _____ Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: [Multiple produced water pits. Foreman indicated only used for emergencies.](#)

Corrective Action _____ Date: _____

Type: Emergency Lined: _____ Pit ID: 100573 Lat: 40.980121 Long: -103.661084

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____ Date: c

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment: _____

Corrective Action _____ Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	<u>Multiple produced water pits. Foreman indicated only used for emergencies.</u>	
Corrective Action		Date:
Type: <u>Emergency</u>	Lined:	Pit ID: <u>100575</u>
	Lat: <u>40.980183</u>	Long: <u>-103.660670</u>
Reference Point: _____	Other: _____	Length: _____
	Width: _____	
<u>Lining:</u>		
Liner Type:	Liner Condition:	
Comment:		
Corrective Action		Date: <u>g</u>
<u>Fencing:</u>		
Fencing Type:	Fencing Condition:	
Comment:		
Corrective Action		Date:
<u>Netting:</u>		
Netting Type:	Netting Condition:	
Comment:		
Corrective Action		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	<u>Multiple produced water pits. Foreman indicated only used for emergencies.</u>	
Corrective Action		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401754811	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4570795
691200408	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4570793