

# Inspection Photos

Operator: BP Production

API: 05-067-08689

Date: 9/10/2018



**Photo 1. View of the project area from the southeastern corner facing center.**





**Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is comprised of grasses and shrubs such as crested wheatgrass (*Agropyron cristatum*), intermediate wheatgrass (*Thinopyron intermedium*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).**







**Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward.**





**Photo 4. View of unused pipe in the northwestern project area.**





**Photo 6. View of disturbed soil in the western project area.**





**Photo 7. View of sediment deposition on the well pad from disturbed soils within the western project area.**





**Photo 8. View of erosional channel forming on the access road where improperly diverted stormwater is eroding the road and downslope.**





**Photo 9. View of area along the access road where roadside ditch is full of sediment and stormwater flows are diverted to the road surface, causing erosion along the road.**





**Photo 10. View of a culvert outlet along the access road where diverted flows are not properly stabilized, energy not sufficiently dispersed, and resulting in erosional channel formation downslope from the culvert.**