

# Inspection Photos

Operator: WPX Energy

API: 05-067-08089

Date: 9/10/2018



**Photo 1. View of the project area from the beginning of the access road facing southward toward the former well pad. Access road is recontoured and seeded/mulched.**



**Photo 2. View of the northern portion of the project area from the northeastern edge facing westward. Revegetation is progressing with grasses and shrubs such as blue grama (*Bouteloua gracilis*) and fourwing saltbush (*Atriplex canescens*), as well as weedy Russian thistle (*Salsola tragus*).**



**Photo 3. View of the reclaimed well pad from the northeastern portion facing center. Location is recontoured, seeded, and mulched.**



**Photo 4. View of the southern portion of the project area from the southeastern project area facing westward.**



**Photo 5. View of seedling quadrat showing successful germination in quadrat sampling.**



**Photo 6. View of seedling quadrat showing sparse germination in quadrat sampling.**