

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2018

Submitted Date:

09/06/2018

Document Number:

689801611**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 447512      Waldron, Emily      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY      State: OK      Zip: 73102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447587	WELL	XX	09/07/2016		057-06582	Peters 0781 13-13H12	DG

**General Comment:**[Routine FIU inspection.](#)

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:	Drilling or recompletion directional sign not posted or information inaccurate, sign not properly sized. No signs on location.		
Corrective Action:	Install sign to comply with Rule 210.a.	Date:	09/11/2018

Emergency Contact Number:	
Comment:	No emergency number on location.
Corrective Action:	Install sign to comply with Rule 210.a.
Date:	09/11/2018

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Dried annual weeds and vegetation present around location on perimeter berm.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/17/2018

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 447587 Type: WELL API Number: 057-06582 Status: XX Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: Juan  
Permit Posted: No Access Sign: No

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: Twin Enviro, Milner

**Comment:** No signs on location. TOO H to run surface casing when inspector was on location. No BOP on location until spudder rig moves off after surface cement jobs. Cuttings being disposed at Twin Enviro.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass					
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401756068	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4572034">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4572034</a>
689801615	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4572030">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4572030</a>