

Inspection Photo
Cox 33-1
API # 045-13388
Inspection # 689301909



Location Photo #1



Location Photo #2,

Inspection Photo
Cox 33-1
API # 045-13388
Inspection # 689301909



Location Photo #3, stained round near separator



Location Photo #4, battery containment

Inspection Photo
Cox 33-1
API # 045-13388
Inspection # 689301909



Location Photo #5, battery containment

