


**Inspection Photo
Bell 34-4C
API # 045-10129
Inspection # 689301911**



Location Photo #1



Location Photo #2, battery containment

**Inspection Photo
Bell 34-4C
API # 045-10129
Inspection # 689301911**



Location Photo #3 repaired holes



Location Photo #4, repaired holes

**Inspection Photo
Bell 34-4C
API # 045-10129
Inspection # 689301911**



Location Photo #5, battery containment