

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2018

Submitted Date:

09/13/2018

Document Number:

689301903**FIELD INSPECTION FORM**
 Loc ID 334916 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|--|
| Elsener, | | COGCC.inspections@caerus oilandgas.com | all Piceance inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 266566 | WELL | PR | 10/17/2003 | GW | 045-09153 | MAGNALL 34-5 (L34) | PR |
| 266567 | WELL | PR | 10/17/2003 | GW | 045-09154 | MAGNALL 34-6 (L34) | PR |
| 266570 | WELL | PR | 11/10/2003 | GW | 045-09156 | MAGNALL 34-12 (L34) | PR |
| 266571 | WELL | PR | 10/13/2003 | GW | 045-09159 | MAGNALL 34-11 (L34) | PR |
| 274962 | WELL | PR | 06/24/2005 | GW | 045-13446 | SCHICKLING 34-5C(L34) | PR |
| 274963 | WELL | PR | 06/21/2005 | GW | 045-13445 | SCHICKLING 34-6C(L34) | PR |

General Comment:

This is a follow up inspection from DOC# 689301671. Required Corrective Action items noted in previous inspections have been satisfied.

Equipment inventory has not changed on location.

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date:

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | panel gates | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | panel gates | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|---------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 6 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 6 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Blowdown tank near pig station. | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 8 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pig Station | # 2 | | |

| | | | |
|-------------------------------|-----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|--------------------------------|----------|------------------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 4 | OTHER | HEATED STEEL AST | | , | |
| Comment: | 250 BBL Centralized battery | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 266566 | Type: | WELL | API Number: | 045-09153 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 266567 | Type: | WELL | API Number: | 045-09154 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 266570 | Type: | WELL | API Number: | 045-09156 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 266571 | Type: | WELL | API Number: | 045-09159 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 274962 | Type: | WELL | API Number: | 045-13446 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 274963 | Type: | WELL | API Number: | 045-13445 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | | | | |
| Berms | | | | | | |
| Ditches | | | | | | |
| Seeding | | | | | | |
| | | Compaction | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| Stained rock in battery containment appears to have been sprayed with microblaze. Weeds on location were also sprayed to control any further growth. | holtzd | 09/13/2018 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---|
| 689301904 | Inspection photo 689301904 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4578597 |